

9

PART - I

PERFORMA FOR THE SAFETY OF SCHOOL BUILDING
(To be filled by the Head of school/ Institution)

- 1 Name of the school : ST. SOLDIER DIVINE PUBLIC SCHOOL
- 2 Location : BEHIND R.E.C (NIT) JALANDHAR
- 3 Plot Area : AMRITA BY PASS ROAD JALANDHAR
- 4 Plinth Area : 2 ACRES, 2 KANAL, 3 MARLA
- 5 Number of Storey : 22959 sq ft
- 6 Year of construction of building : 3 STORY
- 7 Year of construction of building : 1998-1999
- 7 If the building has been constructed under the supervision of the Qualified Engineer, the following details may be given. : YES
- a) Name of the Engineer with Qualification : ENR. RAS KUMAR BSC (CIVIL)
- b) Address of the Engineer : 301, TOWER ENCLAVE JALANDHAR
- c) Detail of structural drawings used in the construction, if available : Attached
- d) Name & Address of Architect with qualification : RAJINDER PAUL B. A.E. Sahota
- 8 Whether the building has been constructed for the purpose of : NEAR BUS STAND
- a) School : SCHOOL
- b) Residential purpose and converted for use as a school. : _____
- 9 Material used for roofs : RCC SLABS M.20
- a) R.C.C. slabs : _____
- b) R.S. Joists & Battens : NOT WOODEN
- c) Wooden Joists & Battens. : _____
- 10 Material used for walls : NO
- a) Mud mortar : YES Central mortar 1:3 RATIO
- b) Cement mortar : NO
- c) Plaster i) Lime mortar : CEMENT MORTAR
- ii) Cement mortar : CONGLOMERATE
- 11 Flooring :- : YES
- a) Conglomerate : _____
- b) Terrazo : _____
- c) Brick paving : NO
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. : Detail drawing attached. YES attached


Signature and Stamp of the Head
of the School
Principal
St Soldier Divine Public School
behind R.E.C (NIT) Jalandhar

PART - II

(TO BE FILLED BY THE S.D.O OF THE P.W.D. B&R DEPARTMENT)

- a) I have visited the above mentioned school on 16/4/2019 and I have visually inspection it from all angles of safety and I find it fit for normal use as a school buildings.
- b) In case any additional alteration or expansion and modification to this building is to be carried out, the same may be carried out, under the supervision of the technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. Immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (Indicate year upto which it can be used). The school building is visually safe & can be occupied upto 31/3/2020

Ref. No. 20 Dated 16/4/15


Sub Divisional Engineer,
P.W.D. B&R Branch
Sub Divisional Engineer
Constn SID 4 P.W.D. B&R
Jalandhar Cantt.

