

VELLAPPALLY ENGINEERS & CONSULTANCY

Vellapally Mattathil Building
S. H. Mount P.O.,
Kottayam-686006
Kerala
Ph: 0481-2791054/2719636



32/2136, 3rd floor,
Colors Establishment Building,
Anjuman Road, Mamangalam,
Kochi-682024
Mob: 9446203680, 8891707959

01/08/2019
Edappally

STABILITY CERTIFICATE

This is to certify that the Educational Building named "S.B.O.A. PUBLIC (Sr. Sec.) SCHOOL" of S.B.I.O.A Education Trust, Chennai, with Building No: 10/406 & 10/407, in Sy No: 641/2, 641/3, 641/4, 642/2, 1212, 1247, 813, 814, 641/1, 290/1, 290/2, 290/3, South Chittoor, Cheranalloor Panchayat, Cheranalloor Village, Ernakulam District. The building is so far structurally stable.

(Total no. of floors G+3+Truss Roof. Approximate plinth area of the building is 50084 Sqft).

Your's Faithfully

Jacob Mathew M.Tech

Reg No: AM 098555 - 7

JACOB MATHEW VELLAPPALLY
M.Tech, CE, AMIE, AFIV
Chartered Engineer - AM 098555-7
Approved Valuer - A - 20614

E-mail : jacobmathew18@gmail.com , vellapallyengineers@gmail.com

VELLAPPALLY ENGINEERS & CONSULTANCY

Vellapally Mattathil Building
S. H. Mount P.O.,
Kottayam-686006
Kerala
Ph: 0481-2791054/2719636



32/2136, 3rd floor,
Colors Establishment Building,
Anjumana Road, Mamangalam,
Kochi-682024
Mob: 9446203680, 8891707959

1. Name of officer: Jacob Mathew, M. Tech, CE, AMIE, AFIV
2. Name of School: S.B.O.A. PUBLIC (Sr. Sec.) SCHOOL
3. Location with Name of Educational District Sub District: Chittoor, Ernakulam
4. Classification of the buildings as specified in Col 4 of the application for fitness Certificate & size: Educational building.
5. Period for which the certificate issued: 1 year
6. Nature of defect if any
 - a) Foundation and basement: No defects observed
 - b) Superstructure: No defects observed
 - c) Doors and window: No defects observed
 - d) Wood work wrought & put up: No defects observed
 - e) Roof: No defects observed
 - f) Flooring: No defects observed
 - g) Miscellaneous (Cracks etc.): No defects observed
7. Any major defects noticed which will render the building unsafe: No defects observed
8. Whether Maintenance works have been done properly: Proper as far as observed.
9. Whether the structure is sound or not for conducting classes: Yes, the building is structurally sound.

- Note: 1. The stability of the structure should be examined also with reference to location, attitude, intensity or wind, exposure to flood etc.,
2. Any additional observations if indeed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 29 July 2019, and found to be fit to conduct classes for the period 1 year for the reason stated above.

Place: Edappally

Signature

Date: 01/08/2019

JACOB MATHEW VELLAPPALLY
Designation: M. Tech, CE, AMIE, AFIV
Chartered Engineer – AM 098555-7
Approved Valuer – A – 20614

E-mail : jacobmathew18@gmail.com , vellapallyengineers@gmail.com